9-7313

12 Volts DC

Connect +12 volts DC to one terminal, and connect −12 volts DC to the other terminal.
It does not matter which terminal is connected to + or −.
This is a series wound motor, it will only rotate in one direction.