
Motor Mount Template

5-1720

Use template to line up gearbox shaft and mounting hole. Hold against mounting surface and mark holes before drilling.



For best results when printing this PDF, set the page scaling to 'NONE' to insure the dimension are the correct size.



12 Volt Motor

CAUTION! IMPORTANT:

5543895 gear motor must be used with a minimum 80 Amp in-line circuit breaker between battery and switch. When replacing a Roll-Rite™ #1031 tarp master motor, its 30 Amp circuit breaker must be replaced with a minimum 80 Amp circuit breaker.

CAUTION! IMPORTANT:

Apply blue medium/high strength thread-locker to gear motor and chrome cover mounting screws.

Gearbox

^{*} Fits common 3-Bolt and 4-Bolt gear motor mounts

